

SC5000 PRIME Firmware Update 1.0.2 Release Notes

IMPORTANT: X1800 PRIME MUST BE UPDATED TO VERSION 1.1 IN ORDER TO USE THIS SC5000 BUILD.

Features:

- Controller Mode support implemented.

Fixes:

- Improved scratching sound at low speeds.
- Fixed an issue where heavy scratching for several hours could result in a player resetting.
- Fixed an issue where remote playlists would show up in a different order than local playlists.
- Fixed an issue where an SD card warning would be shown even though no problem with the SD card reader occurred.
- File transfers over network are now more robust.
- Fixed an issue where in rare circumstances, selecting or ejecting a drive could cause a player to hang.
- Fixed an issue where unplugging and replugging a drive would result in the drive not showing up on a remote player.
- Fixed an issue where loading certain larger databases would show a "DB Corruption Warning" upon source selection.
- Fixed an issue where repeatedly mashing the left hand collection buttons could lead to a hang.
- Fixed an issue where folders ending in " " or "." would result in tracks within that folder showing up as unavailable.
- Splash Screen now shows version number.