

MPC 3.9.1 - Release Notes

MPC 3.9.1 Update

Compatibility

This release is for MPC Key 37 G2, MPC One G2, MPC XL, MPC Live III, MPC Key 37, MPC One+, MPC X Special Edition, MPC Key 61, MPC One, MPC Live II, MPC X, MPC X SE, MPC Live and Force (standalone only).

Desktop Software

The MPC 3 desktop software remains in beta and now includes plug-in versions in the following formats:

- **Audio Unit (AU)**
- **VST3**

Please note that projects created in Standalone Mode on version 3.4 to 3.9.1 are not backward-compatible with the MPC 2.15 desktop software.

Downloading the Firmware Update

You can download the MPC 3.9.1 firmware update in either of the following ways:

- **MPC Standalone Updater:** In standalone mode, connect your MPC to the internet, go to **Preferences > Info**, press **UPDATE**, then select **Online Update**.
- **inMusic Software Center:** Visit [inMusic Software Center | Akai Professional](#) to get the inMusic Software Center (if you don't already have it installed), then download the update from within the inMusic Software Center.

For instructions on installing these updates, please visit our support page [here](#).

General Improvements

- Internal improvements and maintenance updates to support future enhancements and improve overall system stability.

Known Issues

- In rare cases, Audio Mixdown to .WAV can output a blank file.
 - Expert Sleepers ES-9 is known to have distortion on output when used the audio interface with Force and MPC units.
 - Held pad or key events stop playing when changing Sequence or Clip during playback.
 - Cancelling a Save action can fail, causing the TUI and pads to flash.
 - A crash can occur after undoing/redoin Clear Sequence when using Next Seq Step Sequencer mode.
 - When recording Audio Track data that overwrites existing data, the existing audio will be heard briefly on playback loop.
 - After logging out of inMusic Profile, logging in again can fail until Wi-Fi connection is reset.
-